
# HP StorageWorks C2000 FC host bus adapter for AIX release notes

This document contains supplemental information for the HP StorageWorks C2000 FC 2-GB host bus adapter (HBA) for IBM AIX.

For the latest version of these release notes and other HBA documentation, access the HP storage web site: <a href="http://h18006.www1.hp.com/storage/saninfrastructure.html">http://h18006.www1.hp.com/storage/saninfrastructure.html</a>.





### Legal and notice information

© Copyright 2004 Hewlett-Packard Development Company, L.P.

Hewlett-Packard Company makes no warranty of any kind with regard to this material, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Hewlett-Packard shall not be liable for errors contained herein or for incidental or consequential damages in connection with the furnishing, performance, or use of this material.

This document contains proprietary information, which is protected by copyright. No part of this document may be photocopied, reproduced, or translated into another language without the prior written consent of Hewlett-Packard. The information is provided "as is" without warranty of any kind and is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

C2000 FC host bus adapter for AIX release notes

## About this document

This section describes the content reflected in this document, including:

- Intended audience, page 3
- Additional Documentation, page 3

### Intended audience

This document is intended for customers who purchased the C2000 FC HBA running on IBM AIX.

### Additional Documentation

For installation instructions, refer to HP StorageWorks C2000 FC host bus adapter for AIX installation guide. This guide, and additional documentation, including white papers and best practices documents, are available via the HP web site <a href="http://www.hp.com">http://www.hp.com</a>.

# Features and requirements

Table 1 lists the C2000 FC HBA (part number A7539A) features and requirements.

Table 1 Features and requirements

Feature	Requirement
Operating system	IBM AIX 4.3.3 with HACMP 4.4.1
	IBM AIX 5.1 with HACMP 4.4.1, 4.5, and 5.1
	IBM AIX 5.2 with HACMP 4.5 and 5.1
Storage Arrays	Enterprise Virtual Arrays (EVA5000 and EVA3000) with VCS 3.014, 3.020
	Enterprise Modular Arrays (RA8000, MA8000, EMA12000, EMA16000, ESA 12000 Fibre Channel) with ACS 8.8
Fibre Channel switches	For the latest supported switches, refer to the <i>HP StorageWorks SAN design reference guide</i> on the following web site: <a href="http://h18006.www1.hp.com/products/storageworks/san/documentation.html">http://h18006.www1.hp.com/products/storageworks/san/documentation.html</a> .
Drivers	single path-1.5.26.0
	multi-path-1.5.25.3
Firmware	3.02.10
Secure Path	HP StorageWorks Secure Path for IBM AIX 2.0D SP2 or later when connecting to HP Arrays.
Enterprise Backup Solutions	For Enterprise Backup Solutions, refer to the HP StorageWorks Enterprise Backup Solution web site: <a href="http://h18006.www1.hp.com/products/storageworks/ebs/">http://h18006.www1.hp.com/products/storageworks/ebs/</a> .